

SAI NATH UNIVERSITY RANCHI JHARKHAND

PRACTICAL LIST

MACHINE SHOP

- EX-1 Study & Sketch of lathe machine.
- EX-2 Facing, Step turning, Parallel Turning & Taper turning.
- EX-3 Knurling on circular rod.
- EX-4 Drilling on circular rod.
- EX-5 Boring, Counter boring on circular rod.
- EX-6 Taper turning under cutting on circular rod.
- EX-7 Chamfering & Facing on circular rod.
- EX-8 V. thread cutting (Internal and External) .
- EX-9 Square thread Cutting.